





MDI. DT. MRB. 9




**EAC**

# MDI. DT. MRB. 9




A x8  
Spec:  $\varnothing 8 * L30$




C x12  
Spec: 5/16\*45




D x12  
Spec:  $\varnothing 8 * \varnothing 14$




E x1  
Spec: 5#




F x4  
Spec: M8\*L95




G x4  
Spec:




H x4  
Spec: M8



I x4  
Spec:  $\varnothing 38$



J x1  
Spec: 14#



1

2

